



# **APPENDIX I**

## **STORMWATER CONVEYANCE MAPS AND SATELLITE IMAGES**




West Valley View (WV) in September 2020. Approximate Stormwater Outfall sampling location is indicated by red dot along Bear Creek (blue line).




Northridge Terrace (NRT) in September 2020. Approximate Stormwater Outfall sampling location is indicated by red dot near Bear Creek (blue line).






West Valley View (WVV) in January 2021. Debris from homes was still present in area during the rainy winter months.



Northridge Terrace (NRT) in January 2021. Debris from homes was still present in area during the rainy winter months.






West Valley View (WV) in July 2022. Debris from homes has been cleared off and new homes are under construction or completed.



Northridge Terrace (NRT) in July 2022. Debris from homes has been cleared off and new homes are under construction or completed.





## North ridge Terrace





## Colver Rd





## West Valley View

